
## SUNNY & ASSOCIATES

Architect Engineer & Valuer

Sunil Kumar Gera

A.M.I.E. (CIVIL), M.TECH (STR)

Regd. No. M - 150674-3 Chartered Engineer Regd. Engineer M.C. HUDA Regd. Engineer Govt. Approved Valuer



Mob.: 9812176772

RAWLI HAT, MATA CHOWK REWARI-123401 (HR.)

Dated 14-06-25

ref. No. . . R.F. . 14/6...

## SCHOOL BUILDING SAFETY CERTIFICATE

It is certified that Building of school named as "Oxford International School" located at Village Mukundpur Basai, Bolni, Rewari (Hr.) -123401 is in sound, safe and stable condition. I visited the site on 14-06-2025. It is Four Storey Building

R.C.C. frame structure is there. Building materials which has been used are as per B.I.S Norms and specification. Building is earthquake resistant. Estimated future life of building is 50 years. This certificate is provided to whom it may concern.

SUNIL KUMAR
Structural Engineer (M. TECH)
Regd. No. 63/2006 HUDA
Rawli Hat Mata Chowk,
Rewari (Haryana)

Oxford International School Mukundpur Basai (Bolni) Rewas School Code-40877